

2nd April 2020

Our ref: GCU0257001/GW/JW

ESB Networks
Engineering Major Projects
One Dublin Airport Central
Dublin Airport
Cloghran
Co. Dublin

**Subject: Historic Cable Fluid Losses – Location 67
Recommendations from Preliminary Site Assessment**

Dear Sir/Madam

We refer to our Preliminary Site Assessment (PSA) report on the historic loss of cable fluid in North Dock, Dublin Port (Location 67) dated 30th March 2020. The PSA identified the following potential receptors and preliminary risk categories linked to the cable fluid loss¹:

- River Tolka & its estuary (a SPA) - Low
- Water mains - Low
- Bedrock aquifer - Low
- Users of nearby buildings - Very low

Based on the findings of the PSA, no further investigations are considered necessary.

Yours sincerely for
Geosyntec Consultants Ltd


Principal Environmental Engineer

¹ The preliminary risk categories were determined by applying the risk assessment methodology outlined in CIRIA publication C552 (2001).